

**SECRET**



**PHOTO  
INTERPRETATION  
NOTE**

**NATIONAL PHOTOGRAPHIC  
INTERPRETATION CENTER**

**RECONSTRUCTION, HAI PHONG CEMENT PLANT  
NORTH VIETNAM**

25X1

**SECRET**

**Declass Review by NIMA / DoD**

**NPIC/R-47 /71**

**NOVEMBER 1971**

GROUP 1: EXCLUDED FROM  
AUTOMATIC DOWNGRADING  
AND DECLASSIFICATION

WARNING

This document contains information affecting the national defense of the United States, within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

SECRET

NPIC/R-47/71

25X1

RECONSTRUCTION  
HAIPHONG CEMENT PLANT  
NORTH VIETNAM

1. The Haiphong Cement Plant, severely damaged by airstrikes in April 1967, has been almost completely rebuilt. Six of the original seven horizontal rotary kilns were operational

25X1

2. Operations at the plant had been entirely stopped because of extensive damage. One of three rotary kiln buildings was destroyed, one was heavily damaged, and the other sustained minor damage. Two clinker storage buildings were heavily damaged and one moderately damaged. The coal treatment plant, the limestone crushing building, several warehouses, and numerous support buildings were moderately to heavily damaged.

3. Reconstruction of the plant has been slow. One kiln of the westernmost kiln building was repaired and operational [REDACTED] This was the first indication of renewed production at the plant. The second kiln of this two-kiln unit was subsequently operational. [REDACTED] all three kilns of the easternmost kiln building were rebuilt and operating. [REDACTED] smoke was coming from the stack of the central kiln building. One of the two kilns of this unit has been repaired and the other has been removed, possibly in preparation for replacement or repair. Thirteen kiln sections were on the transshipment quay to the east of the plant.

25X1

25X1

25X1

4. Other recent reconstruction included the addition of a new probable coal treatment plant, replacement of a previously destroyed large warehouse, and replacement of the damaged roof of the eastern clinker storage building. Foundations for additional new buildings indicated continuing construction at the facility.

NPIC/IEG/SGD/SAB Project 150066OA

SECRET

25X1

SECRET

NPIC/R-47/71

25X1




FIGURE 1. RECONSTRUCTION AT HAIPHONG CEMENT PLANT

- 2 -

SECRET

25X1

25X1